Test Report No. [redacted] Date: AUG.19,2025 Page1 of 3

SHUYANG CUZI MDF CO.,LIMITED
ZHAXIA MDF INDUSTRY 2-8#, SHUYANG COUNTY, JIANGSU,CHINA

The following sample(s) was/ were submitted

and identified by the client as :

Samples Description :18MM MDF

SGS Ref.No. : [redacted]

Style/Item No. :CUZI

Sample Receiving Date :AUG., 03, 2025

Testing Period :AUG., 03, 2025 TO AUG., 19, 2025

Test Performed :SELECTED TEST(S) ARE REQUESTED BY APPLICANT

Test Result(s) :FOR FURTHER DETAILS, PLEASE REFER TO THE FOLLOWING PAGE(S)

Conclusion :THE TESTS DATA WERE PROVIDED TO CLIENT FOR THEIR OWN ANALYSIS

Test Requested	Conclusion
Formaldehyde Emission Test	Test Result(s)

CUZI MDF | cuzimdf.com

Signed for and on behalf of

SGS-CSTC

Serena Wang

This report is the English version of report no. [redacted]

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions.htm and,for electronic format documents,subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full,without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested .

SGS-CSTC Standards Technical Services (Shanghai) Co.,Ltd.
Testing Center
3rd Building,No.889 Yishan Road Xuhui District,Shanghai China 200233
中国·上海·徐汇区宜山路889号3号楼 邮编: 200233
t E&E (86-21) 61402553 f E&E (86-21)64953679 www.cn.sgs.com
HL: (86-21) 61402594 HL: (86-21)54500353 e sgs.china@sgs.com

Test Report

No. [redacted] Date: AUG.19,2025 Page1 of 3

Test Result(s) :

Description of test sample

Sample NO.	SGS Sample ID	Description
1	[redacted]	WHITE COLOR MDF

Remarks：

(1) 1 mg/kg = 0.0001%
(2) MDL = Method Detection Limit
(3) ND = Not Detected (< MDL)
(4) "-" = Not Regulated

Formaldehyde Emission

Test Method :With Reference EN 717-1:2004 L, analysis was performed by UV-Vis.

Test Item	Unit	MDL	001
Formaldehyde	mg/m³	0.451	0.080
Conclusion		PASS	PASS

Remarks :

(1) Mention Limited:EN13986:2004(E)
(2) Formaldehyde grade E1: ⩽ 0.124 mg/m³ (MDL)
(3) Test results are for reference only


CUZI MDF | cuzimdf.com
CUZI MDF | cuzimdf.com

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions.htm and,for electronic format documents,subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full,without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested .

SGS-CSTC Standards Technical Services (Shanghai) Co.,Ltd.
Testing Center
3rd Building,No.889 Yishan Road Xuhui District,Shanghai China 200233
中国·上海·徐汇区宜山路889号3号楼 邮编: 200233
t E&E (86-21) 61402553 f E&E (86-21)64953679 www.cn.sgs.com
HL: (86-21) 61402594 HL: (86-21)54500353 e sgs.china@sgs.com

Test Report No. [redacted] Date: AUG.19,2025 Page1 of 3

Sample Photo:



CUZI MDF | cuzimdf.com

This photo is only used with the original SGS report

*** End of Report***

CUZI MDF | cuzimdf.com

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/terms_and_conditions.htm and,for electronic format documents,subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full,without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested .

SGS-CSTC Standards Technical Services (Shanghai) Co.,Ltd.
Testing Center
3rd Building,No.889 Yishan Road Xuhui District,Shanghai China 200233
中国·上海·徐汇区宜山路889号3号楼 邮编: 200233
t E&E (86-21) 61402553 f E&E (86-21)64953679 www.cn.sgs.com
HL: (86-21) 61402594 HL: (86-21)54500353 e sgs.china@sgs.com